

2004 Vans RV-6

Specifications

Price	\$ 52,500.00
Year	2004
Serial	23467
Registration	N13EV
TTAF	316.6
Ad Type	For Sale
Location	Hillsboro, KS (M66)
Type	Sold
Summary	<p>ANY REASONABLE OFFER CONSIDERED!</p> <p>Great example of experimental flexibility, this RV6 started out as 6A and was converted to a taildragger at 44 hours TT.</p> <p>Low time excellent quality RV6 equipped for IFR flight while remaining capable for gentlemen's aerobatics. Van's slogan "Total Performance" is not just a saying and this airplane can prove it. This is a great example of the growing Van's fleet. Countless hours of enjoyment and that "RV-Grin" await.</p>
Airframe Details:	TTAF373.6 Airplane converted from RV-6A to RV-6 at 44.6 hours
Engine Detail	<p>Lycoming O-320 E2D with Titan cylinders giving it 160hp, 272 (329) SMOH, S/N 23458-27A.</p> <p>Propeller: Two Blade Sensenich 70CN7S9-0-79, S/N 35153K</p>
Avionics	<p>KLN 89B GPS (IFR), Coupled to Garmin VOR head, Direct Download Port for updating GPS database in panel.</p> <p>King KX-155 Nav/Com, w/glideslope</p> <p>Narco AT 150 Transponder</p> <p>Intercom w/aux input for music</p> <p>Flight Data Systems GT 50 (timer, clock, G meter)</p> <p>Marker Beacons</p> <p>Digital Outside Air Temperature</p> <p>ELT</p> <p>EGT</p>
Exterior	5/10
Interior:	7/10
Maintenance:	<p>Annual Condition Inspection completed (June 19, 2017)</p> <p>IFR – Static/ Transponder completed (Oct 21, 2016)</p>

**Addition Features,
Equipment or
Comments**

Damage History: Yes

- Oct 2005: Previous Owner/Pilot lost control of a/c during landing at touchdown (NTSB)

Repair Info:

A&P: Jim Braden, Braden Aircraft (620) 381-0771 A&P# 405567290

- Sept 2007: (logbook entry) Replaced nose ribs out board both wings, wing skins near tips. Replaced wing tips, landing lights, nav lights, strobes, replaced seat supports.

Changed landing gear from tricycle to tail wheel design. Replaced canopy. Installed new motor mounts. Rebuilt artificial horizon, directional gyro & stdby compass.

- Sept 2007: Installed rebuilt IO-320-E2D engine

Excellent rebuild returned to service with no further incident.

Broker

Name	Joe Benjamin
Email:	joe.b@usaaircraft.com
Designation	Area Aircraft Broker
Address	, Denver, CO 80740 United States
Telephone:	(720) 924-1309
Mobile:	-
Skype:	-

Images

Exterior









Interior



Avionics



any to the Operator's manual for the appropriate maintenance procedures.

